


RigMaster Power Service Procedure: RP13-077

Scope & Procedure

The maximum charging voltage produced by the RigMaster Unit is 14.8 VDC. The purpose of the following procedure is to add a relay to the regulator power supply in order to reduce the voltage drop experienced in the regulator.

Procedure

The following is a schematic of the wiring modification required.



Note

- The short yellow wire is connected to the harness while the long yellow wire is connected to the regulator.
- Cut yellow wire on regulator and engine harness. Connect white to engine side and yellow to regulator side.